


1/34

FIG. 1



2/34

FIG.2






FIG.3




3/34

FIG.4




4/34

FIG.5




5/34

FIG.6




6/34

FIG.7




7/34

FIG.8



8/34

FIG.9



9/34

FIG.10






FIG.11



11/34

FIG.12



12/34

FIG.13




FIG.14A






FIG.14B



14/34

FIG.16



15/34

FIG.17A






FIG.17B




16/34


FIG. 18



17/34

FIG.19






19/34

FIG.21

TYPE OF SERVICE (ToS)	PRIORITY (LEVEL)
000	-
001	-
010	M
011	-
100	H
101	-
110	-
111	-


20/34

FIG.22



21/34

FIG.23



22/34

FIG.24





FIG.25



24/34

FIG.26





FIG.27



25/34

FIG.28






FIG.29





27/34

FIG.31






FIG.32





29/34

FIG.34





FIG.35



31/34

FIG.36






FIG.37



32/34

FIG.38



33/34

FIG.39




FIG.40




FIG.41A

FIG.41B

